

From: "Azhar, Wardah" <azharw@cdmsmith.com>
To: "Zhen, Davis" <Zhen.Davis@epa.gov>
"Sheldrake, Sean" <sheldrake.sean@epa.gov>
CC: "Scott Coffey" <coffeyse@cdmsmith.com>
younghs@cdmsmith.com
Date: 7/31/2018 12:24:41 PM
Subject: Re: Subsurface coring 7/31

Water draining out of holes drilled at the top of core tube.

Core being cut in half for storage, sediment can be seen seeping out.



On Jul 31, 2018, at 9:17 AM, Azhar, Wardah <azharw@cdmsmith.com> wrote:

Core tube being inserted at first location in the International slip, next to pier.

<IMG_5008.JPG>

